

### Grader Issues

	<b>Date</b>	<b>Issue</b>	<b>Cost</b>	<b>Lost Days</b>
1	12/7/2008	strobe lights not wired properly install voltage reducer.	\$185.00	0.5
2	12/11/2008	circle board tooth cracked have pictures welded temp: per nortrax, waiting to hear back from nortrax	\$225.00	1
3	12/12/2008	replaced alternator because of strobe lights weren't wired up right (battery cables loose)	\$385.00	0.5
4	1/5/2009	lost injection pump	\$1,060.00	1
5	1/5/2009	circle board tolerances to tight and will move not move properly needs adj: by maine mil:	\$0.00	0
6	1/14/2009	roof had several holes on it causing it to leak which cause two radio failure	\$1,238.00	2
7	1/17/2009	linkage for side to side molderboard movement came undone	\$125.00	0
8	1/28/2009	replace front wing tower cable because it was to short bt 14"	\$95.00	0.25
9	on delivery	underside of circle board was painted over and never greased causing it to fetch up	\$210.00	0
10	2/29/2009	replaced two fm and am radios	\$150.00	0
11	2/1/2009	several hydraulic leaks	\$82.00	0.5
12	2/8/2009	rear wing tower ram leaking, packing is gone	\$0.00	0
13	2/8/2009	All bolts are loose on the rear wing tower and two are stripped	\$ 100.00	0
<b>Total Warranty paid by Maine Military Authority</b>			<b>\$3,855.00</b>	<b>5.75</b>